

General Environmental Incident Summary

Incident: 1839 **Date/Time Notice:** 12/21/2012 0955 **DEM Incident No:**
Responsible Party: Enbridge Pipelines (North Dakota) LLC
Date Incident: 12/21/2012 **Time Incident:** 0650 **Duration:** 60 minutes
County: Williams **Twp:** 156 **Rng:** 95 **Sec:** 32 **Qtr:** SE SW SE
Lat: 48.28447 **Long:** -102.92240 **Method:** Navigation quality GPS
Location Description: 10351 60th St NW, Tioga, ND 58852

Submitted By: Valerie Lavik

Affiliation:

Address:

City:

State:

Zip:

Received By:

Contact Person: Duane Klabunde
3505 16th St SW
Minot, ND 58701

Distance Nearest Occupied Building: 0.5 Miles

Type of Incident: manifold piping

Description of Released Contaminant: Crude Oil

Volume Spilled: 10.00 gallons

Ag Related: No

EPA Extremely Hazardous Substance: No

Reported to NRC: Unknown

Cause of Incident:

Leak coming from a valve missing a ½ inch plug in manifold area. The leaking area of the manifold was not scheduled for line-fill at this time. It was likely back-filling (gravity feed from Tank 9503) from a valve with possible ice build-up, allowing slow seep by.

Risk Evaluation:

None

of Fatalities: 0

of Injuries: 0

Affected Medium: 03 - soil

Potential Environmental Impacts:

All contaminated soil will be removed and disposed of at an approved facility.

Action Taken or Planned:

Release occurred and was contained within station property (Tank 9503 manifold area). Absorbent pads were put down under piping. All contaminated soil will be removed and hauled to an approved disposal facility.

Wastes Disposal Location: Clean Harbors

Agencies Involved:

Updates

Date: 12/21/2012 ***Status:*** Reviewed - Follow-up Required

Author: Roberts, Kris

Updated Volume:

Notes:

Not an O&G regulated facility. Please follow up and confirm clean up.

Date: 2/7/2013 ***Status:*** Inspection

Author: Stockdill, Scott

Updated Volume:

Notes:

48.284469°N
102.922358°W

Contaminated Soil removed from property, clean up complete.